


# DIGITAL CLAMP METER



## Users Manual

DIGITAL CLAMP METER	
Safety Information	1
Safety Symbols	1
Warning	1
Maintenance Maintenance	2
Introduction	3
Description	3
Panel Description	5
Operation	7
Accuracy Specification	13
General Specifications	16
Auto power off	17
Replace battery	17
Accessory	18

DIGITAL CLAMP METER	
<b>Safety Information</b>	
This meter is designed and manufactured according to the safety requirements set out by the IEC61010-1 standards for electronic test instruments and the hand-held digital multimeters. Its design and manufacture is strictly based on the provisions in the CAT III 600V of IEC61010-1 and the Stipulation of 2-Pollution Grade.	
<b>Safety Symbols</b>	
Risk of danger. Important information. See manual.	
Hazardous voltage.	
Application around and removal from Hazardous Live conductors is permitted.	
Double insulated(Protection class II)	
Earth ground	
<b>warning</b>	
To avoid possible electric shock, personal injury, or death, read the following before using the Meter:	
Use the test leads supplied to ensure operation safety. If required, they must be replaced with test leads of the same model or class.	
Inspect the test leads before use. Do not use them if insulation is damaged or metal is exposed. Check the test leads for continuity. Replace damaged test leads before using. Do not use the Meter if it appears damaged.	
Do not touch the metal tips of the test leads when the meter is connected to the circuit to be measured.	
When Voltage > 60 V dc or ac peak, keep your fingers behind the finger guards.	

DIGITAL CLAMP METER	
<b>Introduction</b>	
This meter 3 3/4 digits with steady operations, fashionable structure and highly reliable measuring instrument. The Meter uses large scale of integrated circuit with double integrated A/D converter as its core and has full range overload protection.	
The meter can perform measurements of AC current, AC/DC voltage, resistance, capacitance as well as continuity and diode test.	
<b>Description</b>	
<b>1. Transformer Jaws:</b>	
Designed to pick up the AC current flowing through the conductor.	
<b>2. Hand Guards:</b>	
To protect user's hand from touching the dangerous area.	
<b>3. Rotary Switch</b>	
Select proper Range and function.	
<b>4. HOLD button</b>	
Press 'hold' button the meter stop updating the LCD panel. LCD display 'H', press the button again, the meter exit hold mode	
<b>5. RAN auto/manual Range button</b>	
Under Voltage, resistance measurement mode, the default mode is autorange, press RAN button switch to manual range, while in manual range mode changes the full-scale range, press this button more than 2 seconds, the meter switch to autorange.	
<b>MAINTENANCE</b>	
Before opening the rear of the meter, disconnect test leads from all sources of electric current.	
Use damp cloth and mild detergent to clean the meter, do not use abrasives or solvents.	
Whenever it is likely that safety protection has been impaired, make the Meter inoperative and secure it against any unintended operation.	
Have the Meter serviced only by qualified service personnel	

DIGITAL CLAMP METER	
<b>6. LCD Screen</b>	
Max Display 3999	
<b>7. INPUT Terminals</b>	
Input positive terminals for all measurement except current measurement, connected with red test leads.	
<b>8. COM Terminals</b>	
Input common terminals for all measurement except current measurement, connected with black test leads	
<b>9. Hz% Frequency and duty Switch Button</b>	
Under AC voltage measurement, press Hz% button to Select a function from voltage, frequency to duty.	
<b>10. SEL :Function selecting button</b>	
In voltage mode, press SEL button to toggle from DCV to ACV; in mode, it is used to select a function from resistance, capacitance, Diode to continuity.	
<b>11. Back light</b>	
Press * button to open the backlight and work light, about 15 seconds will automatically shut down, to trigger the way to work.	
<b>12. Trigger</b>	
Press the lever to open the transformer jaws. When the pressure on the lever is released, the jaws will close.	
<b>13. Transformer Jaws Lighting Bulb</b>	
Switch rotary switch to current position, then turn on lighting Bulb and back light.	

DIGITAL CLAMP METER	
<b>Panel Description</b>	
①Clamp head: AC current transformer	
②Protection device: the design of the protection of the user's hand to avoid touching the dangerous area	
③Measurement function selection turntable	
④The HOLD data hold key.	
⑤The RAN manual / automatic switch of a button.	
⑥The display screen.	
⑦The red pen input.	
⑧The black pen input.	
⑨Hz% frequency duty cycle button.	
⑩The SEL function conversion key.	
⑪ Backlight and working lamp button.	
⑫ clamp head trigger: pressing the button to loosen the clamp head open, automatic closure.	
⑬ Lamp.	

DIGITAL CLAMP METER	
<b>LCD Screen</b>	
① Low battery indicator	
② The automatic range indicator.	
③ The LED indicator.	
④ The on-off detecting indicator.	
⑤ The data retention indicator.	
⑥ The unit of measurement indicator	
⑦ The DC signal measurement indicator	
⑧ Negative indicator.	
⑨ AC signal indicator.	
⑩ The measurement results show.	

DIGITAL CLAMP METER	
<b>Operation</b>	
<b>DC Voltage Measurement</b>	
1. Plug the black test lead into the COM terminals and the red test lead into the INPUT terminals	
2. Set the rotary switch to V, press SEL button switch to DC voltage. Connect the test leads across with the object being measured.	
3. The measured value shows on the display	
<b>Warning!</b>	
Select the highest range if the value scale to be measured in the manual range is unknown	
To avoid harms to you or damages to the Meter from electric shock	

DIGITAL CLAMP METER	
<b>AC Voltage Measurement</b>	
1. Plug the black test lead into the COM terminals and the red test lead into the INPUT terminals	
2. Set the rotary switch to V, press SEL button switch to AC voltage. Connect the test leads across with the object being measured.	
3. The measured value shows on the display	
<b>warning!</b>	
To avoid harms to you or damages to the Meter from electric shock	

DIGITAL CLAMP METER	
<b>AC Current Measurement</b>	
1. Plug the black test lead into the COM terminals and the red test lead into the INPUT terminals	
2. Set the rotary switch to V, press SEL button switch to AC voltage. Connect the test leads across with the object being measured.	
3. The measured value shows on the display	
<b>warning!</b>	
To avoid harms to you or damages to the Meter from electric shock	

DIGITAL CLAMP METER	
<b>warning!</b>	
Select the highest range if the value scale to be measured is unknown, then adjust the rotary switch until get satisfactory resolution.	
To avoid harms to you or damages to the Meter when measuring exposed conductor.	
<b>Measuring Resistance</b>	
1. Plug the black test lead into the COM terminals and the red test lead into the INPUT terminals	
2. Set the rotary switch to Ω, press SEL button switch to Ω. Connect the test leads across with the object being measured.	
3. The measured value shows on the display	
<b>warning!</b>	
At the manual range mode, when only 'OL' is shown on the LCD, it means the measurement has exceeded the range. A higher range should be selected.	
When measuring in-circuit resistance, make sure that the power of the circuit under test has been turned off and that all capacitors have been fully discharged.	

DIGITAL CLAMP METER	
<b>Measuring Diode</b>	
1. Plug the black test lead into the COM terminals and the red test lead into the INPUT terminals	
2. Set the rotary switch to diode symbol, press SEL button switch to diode symbol. Connect the test leads across with the object being measured (Connect the red test lead to the anode and the black test lead to the cathode of the diode).	
3. The Measured value shows on the display	
<b>Testing for Continuity</b>	
1. Plug the black test lead into the COM terminals and the red test lead into the INPUT terminals	
2. Set the rotary switch to continuity symbol, press SEL button switch to continuity symbol. Connect the test leads across with the object being measured.	
3. The buzzer sounds if the resistance of a circuit under test is less than 60 Ω. The buzzer may or may not sounds if the resistance of a circuit under test is between 60 Ω to 120 Ω. The buzzer does not sound if the resistance of a circuit under test is higher than 120 Ω.	
<b>Measuring Capacitance</b>	
1. Plug the black test lead into the COM terminals and the red test lead into the INPUT terminals	

DIGITAL CLAMP METER	
2. Set the rotary switch to V, press SEL button switch to Hz or DUTY mode. Connect the test leads across with the object being measured.	
3. The Measured value shows on the display	
<b>warning!</b>	
When LCD display 'OL', select higher range to measure	
When measuring in-circuit capacitance, make sure that the power of the circuit under test has been turned off and that all capacitors have been fully discharged.	
<b>Measuring temperature</b>	
1. Set the rotary switch to °C.	
2. LCD Display Ambient temperature.	
3. If required, plug thermocouple's (K TYPE) red terminal into INPUT terminal and black terminal into COM terminal, measure object surface or around temperature with thermocouple's probe	
4. The Measured value shows on the display.	
<b>Measuring frequency &amp; duty</b>	
1. Plug the black test lead into the COM terminals and the red test lead into the INPUT terminals	

DIGITAL CLAMP METER																	
<b>DC Voltage</b>																	
<table border="1"> <tr> <th>Range</th> <th>Resolution</th> <th>Accuracy</th> </tr> <tr> <td>400mV</td> <td>0.1mV</td> <td rowspan="2">± (0.8% reading + 2digits)</td> </tr> <tr> <td>4V</td> <td>1mV</td> </tr> <tr> <td>40V</td> <td>10mV</td> <td rowspan="2">± (1.2% reading + 10digits)</td> </tr> <tr> <td>400V</td> <td>0.1V</td> </tr> <tr> <td>600V</td> <td>1V</td> <td>± (1.0% reading + 2 digits)</td> </tr> </table>	Range	Resolution	Accuracy	400mV	0.1mV	± (0.8% reading + 2digits)	4V	1mV	40V	10mV	± (1.2% reading + 10digits)	400V	0.1V	600V	1V	± (1.0% reading + 2 digits)	
Range	Resolution	Accuracy															
400mV	0.1mV	± (0.8% reading + 2digits)															
4V	1mV																
40V	10mV	± (1.2% reading + 10digits)															
400V	0.1V																
600V	1V	± (1.0% reading + 2 digits)															
Input impedance : 10MΩ.																	
Max input Voltage : 600V DC or 600V AC Peak.																	
<b>AC Voltage</b>																	
<table border="1"> <tr> <th>Range</th> <th>Resolution</th> <th>Accuracy</th> </tr> <tr> <td>400mv</td> <td>0.1mV</td> <td rowspan="2">± (1.0% reading + 10digits)</td> </tr> <tr> <td>4V</td> <td>1mV</td> </tr> <tr> <td>40V</td> <td>10mV</td> <td rowspan="2">± (1.2% reading + 10digits)</td> </tr> <tr> <td>400V</td> <td>0.1V</td> </tr> <tr> <td>600V</td> <td>1V</td> <td>± (1.2% reading + 10digits)</td> </tr> </table>	Range	Resolution	Accuracy	400mv	0.1mV	± (1.0% reading + 10digits)	4V	1mV	40V	10mV	± (1.2% reading + 10digits)	400V	0.1V	600V	1V	± (1.2% reading + 10digits)	
Range	Resolution	Accuracy															
400mv	0.1mV	± (1.0% reading + 10digits)															
4V	1mV																
40V	10mV	± (1.2% reading + 10digits)															
400V	0.1V																
600V	1V	± (1.2% reading + 10digits)															
Input impedance : 10MΩ.																	
Frequency response : 40Hz-400Hz																	
Max input Voltage : 600V DC or 600V AC Peak.																	

DIGITAL CLAMP METER																				
<b>DC Current</b>																				
<table border="1"> <tr> <th>Range</th> <th>Resolution</th> <th>Accuracy</th> </tr> <tr> <td>4A</td> <td>0.001A</td> <td rowspan="2">± 0.5% reading + 20digits ≤ 0.5A ± (3.0% reading + 10 digits)</td> </tr> <tr> <td>40A</td> <td>0.01A</td> </tr> <tr> <td>400A</td> <td>0.1A</td> <td rowspan="2">± (2.5% reading + 10 digits)</td> </tr> <tr> <td>600A</td> <td>1A</td> <td>± (1.5% reading + 5 digits)</td> </tr> </table>	Range	Resolution	Accuracy	4A	0.001A	± 0.5% reading + 20digits ≤ 0.5A ± (3.0% reading + 10 digits)	40A	0.01A	400A	0.1A	± (2.5% reading + 10 digits)	600A	1A	± (1.5% reading + 5 digits)						
Range	Resolution	Accuracy																		
4A	0.001A	± 0.5% reading + 20digits ≤ 0.5A ± (3.0% reading + 10 digits)																		
40A	0.01A																			
400A	0.1A	± (2.5% reading + 10 digits)																		
600A	1A		± (1.5% reading + 5 digits)																	
Frequency response : 50Hz-60Hz																				
Max Input Current: Full Range × 120% and measuring time less than 60 seconds.																				
<b>Resistance</b>																				
<table border="1"> <tr> <th>Range</th> <th>Resolution</th> <th>Accuracy</th> </tr> <tr> <td>400Ω</td> <td>0.1Ω</td> <td rowspan="2">±(1.2% reading + 2digits)</td> </tr> <tr> <td>4kΩ</td> <td>0.001kΩ</td> </tr> <tr> <td>40kΩ</td> <td>0.01kΩ</td> <td rowspan="2">±(2.0% reading + 5digits)</td> </tr> <tr> <td>400kΩ</td> <td>0.1kΩ</td> </tr> <tr> <td>4MΩ</td> <td>0.001MΩ</td> <td></td> </tr> <tr> <td>40MΩ</td> <td>0.01MΩ</td> <td></td> </tr> </table>	Range	Resolution	Accuracy	400Ω	0.1Ω	±(1.2% reading + 2digits)	4kΩ	0.001kΩ	40kΩ	0.01kΩ	±(2.0% reading + 5digits)	400kΩ	0.1kΩ	4MΩ	0.001MΩ		40MΩ	0.01MΩ		
Range	Resolution	Accuracy																		
400Ω	0.1Ω	±(1.2% reading + 2digits)																		
4kΩ	0.001kΩ																			
40kΩ	0.01kΩ	±(2.0% reading + 5digits)																		
400kΩ	0.1kΩ																			
4MΩ	0.001MΩ																			
40MΩ	0.01MΩ																			
Overloading protection: 600V DC or 600V AC peak																				

DIGITAL CLAMP METER																				
<b>Capacitance</b>																				
<table border="1"> <tr> <th>Range</th> <th>Resolution</th> <th>Accuracy</th> </tr> <tr> <td>40nF</td> <td>0.01nF</td> <td rowspan="2">± (3.0% reading + 10 digits)</td> </tr> <tr> <td>400nF</td> <td>0.1nF</td> </tr> <tr> <td>4uF</td> <td>0.001uF</td> <td rowspan="2">± (3.0% reading + 10 digits)</td> </tr> <tr> <td>40uF</td> <td>0.01uF</td> </tr> <tr> <td>100uF</td> <td>0.1uF</td> <td></td> </tr> </table>	Range	Resolution	Accuracy	40nF	0.01nF	± (3.0% reading + 10 digits)	400nF	0.1nF	4uF	0.001uF	± (3.0% reading + 10 digits)	40uF	0.01uF	100uF	0.1uF					
Range	Resolution	Accuracy																		
40nF	0.01nF	± (3.0% reading + 10 digits)																		
400nF	0.1nF																			
4uF	0.001uF	± (3.0% reading + 10 digits)																		
40uF	0.01uF																			
100uF	0.1uF																			
Overloading protection: 600V DC or 600V AC peak																				
<b>frequency &amp; duty</b>																				
<table border="1"> <tr> <th>Range</th> <th>Resolution</th> <th>Accuracy</th> </tr> <tr> <td>50Hz</td> <td>0.01Hz</td> <td rowspan="2">± (1.0% reading + 3 digits)</td> </tr> <tr> <td>500Hz</td> <td>0.1Hz</td> </tr> <tr> <td>5kHz</td> <td>0.001kHz</td> <td rowspan="2">± (3.0% reading + 3 digits)</td> </tr> <tr> <td>50kHz</td> <td>0.01kHz</td> </tr> <tr> <td>100kHz</td> <td>0.1kHz</td> <td></td> </tr> <tr> <td>0.1~99.9%</td> <td></td> <td></td> </tr> </table>	Range	Resolution	Accuracy	50Hz	0.01Hz	± (1.0% reading + 3 digits)	500Hz	0.1Hz	5kHz	0.001kHz	± (3.0% reading + 3 digits)	50kHz	0.01kHz	100kHz	0.1kHz		0.1~99.9%			
Range	Resolution	Accuracy																		
50Hz	0.01Hz	± (1.0% reading + 3 digits)																		
500Hz	0.1Hz																			
5kHz	0.001kHz	± (3.0% reading + 3 digits)																		
50kHz	0.01kHz																			
100kHz	0.1kHz																			
0.1~99.9%																				
Input impedance : 10MΩ.																				
Max input Voltage : 600V DC or 600V AC Peak.																				

DIGITAL CLAMP METER							
<b>Diode</b>							
<table border="1"> <tr> <th>Range</th> <th>Resolution</th> <th>Accuracy</th> </tr> <tr> <td>1mV</td> <td></td> <td>Display forward Voltage (Open circuit voltage approximate 1.5V)</td> </tr> </table>	Range	Resolution	Accuracy	1mV		Display forward Voltage (Open circuit voltage approximate 1.5V)	
Range	Resolution	Accuracy					
1mV		Display forward Voltage (Open circuit voltage approximate 1.5V)					
Overloading protection: 600V DC or 600V AC peak							
<b>continuity</b>							
<table border="1"> <tr> <th>Range</th> <th>Resolution</th> <th>Accuracy</th> </tr> <tr> <td>0.1Ω</td> <td></td> <td>Less than about ≤60Ω will beep (Open circuit voltage approximate 0.45V)</td> </tr> </table>	Range	Resolution	Accuracy	0.1Ω		Less than about ≤60Ω will beep (Open circuit voltage approximate 0.45V)	
Range	Resolution	Accuracy					
0.1Ω		Less than about ≤60Ω will beep (Open circuit voltage approximate 0.45V)					
(warning: The buzzer may or may not sounds if the resistance of a circuit under test is between 60 Ω to 120 Ω. The buzzer does not sound if the resistance of a circuit under test is higher than 120Ω.)							
Overloading protection: 600V DC or 600V AC peak							
<b>General Specifications</b>							
Maximum voltage including transient overvoltage between any terminals and grounding: CATIII 600VDC or 600V AC peak							
Display : LCD screen, max reading 3999							
Measurement principle: double integrated A/D converter							
Range mode: Auto Range or manual Range							
Measurement Speed: (2.5-3 times) / Second							
Unit display: Sign							
Polarity Display: -							
Overloading: 'OL'							

DIGITAL CLAMP METER	
<b>HOLD : Display</b>	
Low Battery indication: Display	
Power supply: DC1.5V X3 SIZE AAA battery.	
Dimensions : 208mm×78mm×35mm	
Weight: <340g (including Battery)	
Max. Jaw Size: 26mm diameter	
Operating: 5°C-35°C	
Storage: -10°C-50°C	
<b>Auto power off</b>	
To preserve battery life, the Meter automatically turns off if you do not turn the rotary switch or press any button for around 15 minutes. The Meter can be activated by pressing SEL button	
<b>Replace battery</b>	
Make sure the transformer jaw and the test leads are disconnected from the circuit being tested before opening the case bottom. Check battery has been installed and battery cover been screwed before use. replace the batteries as soon as the battery indicator appears.	
<b>Performs replace battery</b>	

DIGITAL CLAMP METER	
1. Disconnect test leads from live circuit, switch rotary switch to 'OFF' position.	
2. Remove test leads from input terminals	
3. Remove the screw from the battery cover, and separate the battery compartment from the case bottom. Replace the battery with 3pcs of new 1.5V (AAA) battery.	
4. Rejoin the case bottom and the battery cover, and reinstall the screw.	
<b>Accessory</b>	
manual	1
Test leads	2
K-type temperature probe	1
1.5V SIZE AAA Battery	3

DIGITAL CLAMP METER	
<b>DC Voltage Measurement</b>	
1. Plug the black test lead into the COM terminals and the red test lead into the INPUT terminals	
2. Set the rotary switch to V, press SEL button switch to DC voltage. Connect the test leads across with the object being measured.	
3. The measured value shows on the display	
<b>warning!</b>	
Select the highest range if the value scale to be measured in the manual range is unknown	
To avoid harms to you or damages to the Meter from electric shock	