right angle™

DS500 Docking Station Drawer
## Installation Instructions
Warranty: raproducts.com/warranty

| Power Driver with Adjustable Torque | #2 Phillips Head Driver Bit | #2 Square Head Driver Bit | 5/64" Drill Bit | Square | Tape Measure |

51708 ①

50072 ②

50215 ③

Front

2.875

16.500

1.000

Drill 5/64" pilot holes 1/2" deep.

10.500

22"
Minimum
Mounting
Depth
Required

1.000

Bottom of Worksurface

Wire management ties. Bundle wires; then attach.

③

①

②

Put one screw **1** in each bracket and fully tighten. Operate the drawer. If it is binding, loosen the screws and adjust the drawer until it does not bind. Tighten the screws and drive in four more screws.