Instruction Sheet
## Cyclops 2 Cable Jacket Stripper
P/N 15010

Application

CYCLOPS 2

Stripping tool for removing cable jackets from twisted pair cable (UTP/STP), single & multi-core cables and fiber optic cable.

Accepts cable diameters to .43" (11 mm) diameter.

Self adjusting.

Side Grips

Ring pull for middle finger

1. Opening the tool

Pull on the ring with the middle finger and push on the side grips with the thumb and forefinger.

2. Inserting the Cable

Open the tool and insert the length of cable to be stripped.

3. Operation

THIN Insulation

Rotate in direction of MIN arrow

THICK Insulation

Rotate in direction of MAX arrow

4. Removing the insulation

Open and remove the tool from the cable.

Bend and pull off the outer insulation.

PLATINUM TOOLS

www.platinumtools.com   Ph: 805.532.0145