

SPLICE TRAY INSTRUCTIONS | ST-PA-12

1. General

This document covers the installation of Total Cable Solutions Splice Tray Kit ST-PA-12. The ST-PA-12 stores up to 12 fusion splices from up to 12 buffer tube attachment points. Entrance of buffer tubes is located on both ends for In-Line or Butt configurations while maintaining minimum fiber bend requirements. The tray is designed to accommodate single fusion splicing using 40mm (ST-FPS-40mm-50) or 60mm (ST-FPS-60mm-50) protection sleeves.

2. Assembly Contents

(1) ST-PA-12 Plastic base and cover, (4) Velcro® dots, (6) Foam cable protectors,(4) Tie-wraps, and (1) Splice Label.

3. Preparing the Organizer

The ST-PA-12 is stackable for easy splicing among multiple trays. Simply remove plastic cover and snap in additional tray(s).







WARNING!

Verify that all light/laser sources are turned off while splicing fibers. Make sure a minimum bend radius is maintained.

4.1 Preparing the Fiber

Prepare the fiber bundles per Manufacturer's recommended procedure, leaving 44" exposed for splicing.

4.2 Routing the Fiber

Route fiber bundles to splice tray and secure using supplied tie-wraps. Ensure not to over tighten tie-wraps. Recommendation: for buffer tubes directly routed to a splice tray, install a 1" section of 1/8" spiral wrap or protective foam around the tube to help secure the tube from slipping from the tie-wraps.







Total Cable Solutions • www.TotalCableSolutions.com • Tel: 1.888.235.2097 • Fax: 937.528.2861


1 (of 2)



4.3 Splicing the Fibers

Follow company procedures for splicing and protecting fibers. After splicing, store the completed splice and then store the slack as required. Ensure all stored slack is coiled properly inside the organizer. Install cover, making sure no exposed fibers can be accidentally pinched.





6. Tray Storage

The tray can be stored by stacking and snapping multiple units together. Secure tray(s) into panel with Velcro® strap included in most TCS enclosures or use the enclosed self adhesive Velcro® dots. Follow all tray storage instructions as provided in the specific closure or enclosure installation manual.

5. Labeling

Included in the splice tray kit is a self adhesive label that is affixed to tray for fiber identification.

IMPORTANT NOTICE

All statements, technical information and recommendations related to the Seller's products are based on information believed to be reliable, but the accuracy or completeness thereof is not guaranteed. Before utilizing the product, the user should determine the suitability of the product for its intended use. The user assumes all risks and liability whatsoever in connection with such use. Any statements or recommendations of the Seller which are not contained in the Seller's current publications shall have no force or effect unless contained in an agreement signed by an authorized officer of the Seller. The statements contained herein are made in lieu of all warranties, express or implied, including but not limited to the implied warranties of merchantability and fitness for a particular purpose which warranties are hereby expressly disclaimed.

SELLER SHALL NOT BE LIABLE TO THE USER OR ANY OTHER PERSON UNDER THE LEGAL THEORY, INCLUDING BUT NOT LIMITED TO NEGLIGENCE OR STRICT LIABILITY, FOR ANY INJURY OR FOR ANY DIRECT OF CONSEQUENTIAL DAMAGES SUSTAINED OR INCURRED BY REASON OF THE USE OF ANY OF THE SELLERS PRODUCTS THAT WERE DEFECTIVE.

2 (of 2)

Total Cable Solutions • www.TotalCableSolutions.com • Tel: 1.888.235.2097 • Fax: 937.528.2861