Installation Instructions

SMC11 Magnetic Line Contactor

Electrical Ratings:

SUPCO	Coil	Full Load	Resistive	Locked	
No.	Voltage	Amps	Amps	Rotor Amps	Switching
SMC11	24	30	30	125	DPST

Coil Data:


Coil	Pick-up	Max
Volt	Hot	Cold
24	20.5	19.2

Caution: Disconnect power before servicing equipment.


Installation:

- 1. Mount new SUPCO contactor in any position, except with metal mounting base on top. Optional universal mounting bracket kit, SUPCO part no. SMC11B, includes bracket, push-on terminal adapters and screws to facilitate mounting.
- 2. Refer to diagrams below and wire accordingly.
- 3. Restore power and check operation.

schematic:



typical wiring:



Installation Instructions

SMC11 Magnetic Line Contactor

Electrical Ratings:

SUPCO	Coil	Full Load	Resistive	Locked	
No.	Voltage	Amps	Amps	Rotor Amps	Switching
SMC11	24	30	30	125	DPST

Coil Data:


Coil	Pick-up	Max	
Volt	Hot	Cold	
24	20.5	19.2	

Caution: Disconnect power before servicing equipment.


Installation:

- 1. Mount new SUPCO contactor in any position, except with metal mounting base on top. Optional universal mounting bracket kit, SUPCO part no. SMC11B, includes bracket, push-on terminal adapters and screws to facilitate mounting.
- 2. Refer to diagrams below and wire accordingly.
- 3. Restore power and check operation.

schematic:



typical wiring:



example illustrates 24V control circuit



