

**Toll Free: 87 PERMATEX** (877-376-2839)

10 Columbus Blvd., Hartford, Connecticut 06106

6875 Parkland Boulevard, Solon Ohio 44139

# **Technical Data Sheet**

# Permatex® Rust Treatment

AAM Revised 07/14

## PRODUCT DESCRIPTION

Permatex® Rust Treatment is a fast drying milky white latex coating that is applied to rusted metal to stop rust and protect the surface.

## **PRODUCT BENEFITS**

- Kills old rust prevents new rust
- No sandblasting simply wire brush to remove loose rust, clean off any oil, dirt or grease and brush on Permatex® Rust Treatment.
- Works on damp rusty metal
- Changes from a white liquid to a tough, black coating in the presence of iron oxides
- Safe, non-flammable, low toxicity


# **TYPICAL APPLICATIONS**

- Destroys rust on all automotive applications
- Trucks, trailers, storage tanks
- Pipes, valves, fittings in refineries, tankers, power plants, domestic and commercial heating/cooling plants
- Fences, guard rails, conveyors, supports
- Overhead cranes, booms, floor grating, duct work
- Outdoor advertising sign supports/frames, municipal, and highway sign posts and frames
- Bulkheads, overheads, decks, hatch covers, stacks on ships (topcoat with appropriate marine paint)
- Agricultural equipment, harvesters, plows, discs, tractors, corn pickers, etc.
- Snow removal equipment in highway department maintenance yards

#### **DIRECTIONS FOR USE**

NOTE: This product is not recommended for use under exterior automotive sheet metal finishes. May cause blistering or peeling.

- Remove oil grease and dirt.
- Wire brush surface to remove loose rust, mill scale and
- Rinse with water to remove powder and solubles.
  - NOTE: Light rust should be firmly bonded to the surface of the metal and not easily removed by wiping. Rust Treatment will easily convert properly prepared bare metal surfaces.
- Mix thoroughly before using.
- Pour into a clean container for easy application by brushing or apply directly to surface and brush out.
- Brush, roll or sponge on liberally. Spray application is recommended for large areas. Airless spray equipment is faster and provides more effective conversion due to improved surface penetration. Conventional air-spray equipment may be used, but Rust Treatment may require thinning up to 10% with water for proper



- A purple to black coating will begin to appear within 20 minutes depending on temperature and humidity conditions. Uneven color indicates the need for additional coats. For maximum protection, application of 2 coats for 4 mils dry film thickness is recommended. Apply a second coat within 15 - 30 minutes of the first coat. Allow a minimum of 24 hours drying time before priming or applying a finish coat.
- NOTE: After complete drying, Permatex Rust Treatment must be topcoated for maximum Most finish paints will not require any durability. additional primer. However, water based paints and metal filled paints will require a solvent based primer on top of the Rust Treatment coating, prior to applying the finish coat.

# For Cleanup

- When Rust Treatment dries, it is extremely difficult to remove; therefore spatters should be cleaned up as they occur.
- Brushes, rollers and other tools and spatters should be cleaned immediately with water and detergent. Rust Treatment is difficult to remove when dry.
- Spray equipment must be flushed immediately with mild detergent and water then rinsed with fresh water.
- If Rust Treatment is spilled on clothes, the garment should be soaked with cold tap water as soon as possible and Rust Treatment washed out before it dries. Do not use ammonia, strong alkali detergents or hot water to clean up.
- Hands and nails should be cleaned with soap and water using a nailbrush. Black stains from iron-contaminated

Rust Treatment can be removed from the hands with a mixture of 1 part liquid household bleach and 4 parts of tap water, followed by washing with soap and water. Spills of Rust Treatment should be flushed with large amounts of cold tap water.

## PROPERTIES OF UNCURED MATERIAL

Typical Value
Synthetic latex resin
Milky off-white liquid

Appearance Milky off-white Odor Mild odor Specific Gravity 1.20

Viscosity Flow similar to SAE 60 Motor Oil

Flash Point, TCC None

## **GENERAL INFORMATION**

Chemical Type

This product is not recommended for use in pure oxygen and/or oxygen rich systems.

For safe handling information on this product, consult the Material Safety Data Sheet, (MSDS).

# **ORDERING INFORMATION**

Part Number	Container Size
81775	8 fl. oz. bottle
81773	16 fl. oz. bottle

## **STORAGE**

Products shall be ideally stored in a cool, dry location in unopened containers at a temperature between 8° and 28°C (46° and 82°F) unless otherwise labeled. Optimal storage is at the lower half of this temperature range. To prevent contamination of unused product, do not return any material to its original container.

# NOTE

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. Permatex, Inc. specifically disclaims all warranties expressed or implied, including warranties of merchantability or fitness for a particular purpose, arising from sale or use of Permatex, Inc. products and disclaims any liability for consequential or incidental damages of any kind, including lost profits. This product may be covered by one or more United States or foreign patents or patent applications.