


R-Style Delta Light Table Assembly Instructions

Warranty: raproducts.com/warranty



Tools Required for Assembly

- A. Power Driver with Adjustable Torque
- B. #2 Phillips Head Driver Bit (Recommended)
- C. #2 Square Head Drive Bit (Recommended)







Hardware and Tools Included for Assembly (may have extra)

- D. #6 X 5/8" Phillips Head Machine Bolt x4
- E. Wood Screw x Varies
- F. #6 X 2"Phillips Head Machine Bolt x4









Table Parts


- G. Left Leg x1
- H. Right Leg x1
- I. Modesty Panel x1






Step 1

• Attach the modesty panel to the legs with four machine bolts.










Step 2


• Attach the legs to the worksurface with four machine bolts.

Note: the worksurface has threaded inserts for the machine bolts.











Step 3

• Attach the modesty panel to the worksurface with wood screws.









Step 4

• Finished table.

