




1. Remove insulation equivalent to 1/2 connector length.




2. Wire brush stripped end of cable. Insert conductors and tighten screws according to the chart below. Flex each cable and re-torque each screw.



3. Center connector over one side of gel-filled cover.



4. Snap shut both looks. (Use pliers if needed to close).



Part	Wire Range	Torque Req.
ESGTS-2	#2 - #14 AWG	80 in* lb
ESGTS-2/0	#2/0 - #14 AWG	120 in* lb