

NEBO[®]

DAVINCI™ 5000L

Before operating or charging, open the battery compartment and remove the round battery spacer disc.



RECHARGEABLE

Unscrew the base and use the included charging cable to recharge the unit.

Power button will indicate battery level.

POWER INDICATOR

Steady Orange: Battery more than 25%

Flashing Orange: Battery less than 25%

CHARGING INDICATOR

Pulsing Green: Battery charging

Steady Green: Battery fully charged



OPERATION

Press & release power button to turn the unit off and on and cycle through light modes:

High > Medium > Low > Off

When light is ON for 8 seconds or longer, the next button press will turn the unit off.

Strobe: Double-tap button

Direct-to-Low: From OFF, press and hold power button

Smart Power Control™ (SPC) seamlessly transitions through light modes.



3X ZOOM

Twist the head to narrow or widen the light beam.



POWER BANK

To charge your phone or other USB device, simply plug the device into the USB port.

BATTERY

This unit is powered by a Li-Ion battery.

WARNING!

Unit can become hot while in use. Keep the crown away from surfaces until the unit cools.

Smart Power Control™ (SPC) seamlessly transitions through light modes.

PRODUCT GUARANTEE



If you experience a problem, please do not return to your local store. Contact our Customer Service team at **800-255-6061** or www.nebotools.com/contact

For more information, detailed video instructions, and warranty registration, visit NEBOTOOLS.com