





# 300CPU Holder Assembly Instructions

Warranty: [raproducts.com/warranty](http://raproducts.com/warranty)





Power Driver with  
Adjustable Torque



#2 Phillips Head  
Driver Bit




#2 Square Head  
Driver Bit



Flat Blade  
Driver Bit




T-20 Torx Head  
Driver Bit



Square



Tape Measure




1

50200 x2



2

50951 x2




3

52855 x4




4


50006 x2



1




Remove paper strips  
and place track as  
shown below.




Track square  
and back  $\frac{3}{8}$ "

2



Item 52855 3 may be  
substituted for item 50006  
4 if tamper resistant is not  
required.





Item 50200 1 may be substituted for Item 50951 2 if tamper resistant is not required.

Padlock not provided.

**3**