


## Cable Counter Lid Instructions



1. Prior to securing the Cable Counter Lid, feed the Cable through the Bushing on the back of the lid as shown. Be sure enough Cable protrudes to grab.
2. Secure the Lid to the Bucket.
3. Push the button on the counter to zero the cable counter before every use.
4. Pull the cable to the desired length and cut the cable, leaving enough to grab for the next use.