

# INSTALLATION INSTRUCTIONS

## SSRT3165- RED SILICONE TUBING

SSRT3165 tubing temperature rating is  
-100°F to 500°F (-73°C to 260°C)

Burst Pressure: 60 PSI

Working Pressure: 20 PSI

Outside Diameter: 5/16"

Inside Diameter: 3/16"

1. Always disconnect power before working on the equipment.
2. Remove the old tubing and measure the length.
3. Clean the barbs to ensure there is no old hose or debris.
4. Cut new hose to proper length. Measure length from old hose if it is still intact.
5. Attach hose to barbs.
6. Reconnect power and test.

800.333.9125 - [techsupport@supco.com](mailto:techsupport@supco.com) - [www.supco.com](http://www.supco.com)



Disconnect power before  
servicing equipment.